



Clean & Boost[®]

Instructions

1. With the enclosed flow-thru brush tip, apply **Clean & Boost[®]** to the surface to be cleansed. Surface should be completely saturated with **Clean & Boost[®]**.
2. Using the delivery brush tip, agitate the **Clean & Boost[®]** on the surface for 10 seconds
3. Rinse thoroughly